

Cust.	1093416	Delhivery Limited			
Order	56975	Dealer	69400		
Repair Date	29/08/2025	Closed Date	30/08/2025	Order Delv.dt	29/08/2025
Chassis/SL No.	8-992520	Regn.	KA51AK7764	Vehicle Delv.dt	14/11/2024
Mileage	203629	Operation Hrs	4682	ServiceType	0
Contr.ID	2509120514	Contr.Startdt	01/01/2025	Contr.Expirydt	31/12/2029

Line Type	Lab/Part	Payment Code	Description	Qty
Job - 1;2 lac kms schedule service				
Parts	OL85153938S	8	VOLVO ENGINE OIL VDS-5	38
Parts	VO23759508	8	OIL FILTER KIT	2
Parts	VO24633960	8	FILTER KIT	1
Parts	VO24137737	8	FILTER KIT	1
Parts	OL1161995-I	8	Volvo Power Steering Oil	6
Parts	VO20580233	8	Power Steering Oil Filter	1
Parts	VO23690622	8	APM filter cartridge	1
Parts	VO84425617	8	Climate Unit Filter	1
Parts	VO24111100	8	FILTER	1
Parts	VO24429533	8	CONNECTION PIPE	1
Parts	VO21794321	8	ADJUSTING SCREW	1
Parts	VO1677396	8	NUT	1
Parts	VO983472	8	CABLE TIE	2
Standard Times	17746-2	8	Annual service.	2.2
Standard Times	17513-2	8	Engine, oil and filter, replace	0.8
Standard Times	23354-2	8	Fuel and water separator filter, replace	0.3
Standard Times	56126-2	8	Air drier, drier insert, replace	0.5
Standard Times	25479-4	8	Tank Filter, Adblue, replace. AdBlue tank, removed	0.1
Standard Times	17010-2	8	Connect-disconnect of diagnostic tool	0.2
Standard Times	17012-3	8	Fault codes, reading	0.2
Standard Times	23003-3	8	Fuel system, bleeding	0.2
Standard Times	86302-1	8	Bottom guard plate, oil pan, remove	0.2
Standard Times	86303-1	8	Bottom guard plate, oil pan, install	0.3
Standard Times	17000-2	8	Additional checking done	1
Standard Times	56126-2	8	Air drier, drier insert, replace	0.5
Standard Times	21442-1	8	Rocker arm shaft, install	1.6
Standard Times	21440-1	8	Rocker arm shaft, remove	0.5
Standard Times	64514-2	8	Oil and filter, power steering, replace	0.7
Standard Times	87208-3	8	Air conditioning air filter, replace	0.1
Standard Times	17026-3	8	Program control unit (RCIOM)	0.2
Standard Times	17026-3	8	Program control unit (CCIOM)	0.2
Standard Times	17026-3	8	Program control unit (FCIOM)	0.2

Job - 2;Wiper water not spreading properly

Text 8 Wiper water work not done

Job - 3;Left side indicator not working

Text 8 Lhs indicator work not done

Cust.	1093416	Delhivery Limited			
Order	5000	Dealer	692025		
Repair Date	09/07/2025	Closed Date	15/07/2025	Order Delv.dt	09/07/2025
Chassis/SL No.	8-992520	Regn.	KA51AK7764	Vehicle Delv.dt	14/11/2024
Mileage	162859	Operation Hrs	3733	ServiceType	1
Contr.ID	2509120514	Contr.Startdt	01/01/2025	Contr.Expirydt	31/12/2029

Line Type	Lab/Part	Payment Code	Description	Qty
Job - 1;horn not working				
Standard Times	36202-2	9	Electric horn, replace	0.2
Text		9	TFAR No - 692000-OR-2025-69685	
Text		9	Causal S/N. -10R-064939 28R-000584 New SL/N-10R-064939 28R-000584	
Parts	VO23993587	9	HORN	1

Cust.	1093416	Delhivery Limited			
Order	917	Dealer	694051		
Repair Date	25/04/2025	Closed Date	25/04/2025	Order Delv.dt	25/04/2025
Chassis/SL No.	8-992520	Regn.	KA51AK7764	Vehicle Delv.dt	14/11/2024
Mileage	109102	Operation Hrs	2504	ServiceType	0
Contr.ID	2509120514	Contr.Startdt	01/01/2025	Contr.Expirydt	31/12/2029

Line Type	Lab/Part	Payment Code	Description	Qty
Job - 1;Coolant Level top-up require-P.C 08				
Parts	IN224754666	8	COOLANT-VCS2 210L	2
Text		8	C1- Coolant level check. C2- Coolant level found low and needs to be top-up the level. C3- Coolant level top-up done.	

Cust.	1093416	Delhivery Limited			
Order	919	Dealer	694051		
Repair Date	25/04/2025	Closed Date	25/04/2025	Order Delv.dt	25/04/2025
Chassis/SL No.	8-992520	Regn.	KA51AK7764	Vehicle Delv.dt	14/11/2024
Mileage	109102	Operation Hrs	2504	ServiceType	1
Contr.ID	2509120514	Contr.Startdt	01/01/2025	Contr.Expirydt	31/12/2029

Line Type	Lab/Part	Payment Code	Description	Qty
Job - 1;Campaign-S4470 due, MJC-63682				
Standard Times	28005-2	9	EMS/ECM, software update	0.2

Service History

Page 3 / 6

Standard Times	17010-2	9	Connect-disconnect of diagnostic tool	0.2
----------------	---------	---	---------------------------------------	-----

Cust.	1093416	Delhivery Limited		
Order	55877	Dealer	69400	
Repair Date	11/04/2025	Closed Date	23/04/2025	Order Delv.dt 11/04/2025
Chassis/SL No.	8-992520	Regn.	KA51AK7764	Vehicle Delv.dt 14/11/2024
Mileage	105288	Operation Hrs	2418	ServiceType 1
Contr.ID	2509120514	Contr.Startdt	01/01/2025	Contr.Expirydt 31/12/2029

Line Type	Lab/Part	Payment Code	Description	Qty
-----------	----------	--------------	-------------	-----

Job - 1;L.H.S. HEADLIGHT GLASS BROKEN

Sublet		0	Front underrun guard remove repaired & refit	
Sublet		0	Painting charges	
Parts	VO948211	0	CABLE TIE	3
Parts	VO980881	0	CABLE TIE	2
Parts	VO24189495	0	INDICATOR LAMP	1
Parts	VO21303956	0	Wheel Nut	10
Parts	VO24075964	0	WHEEL STUD	10

Job - 3;L.H.S FOOT REST BROKEN

Sublet		0	Lhs bumper corner remove repair & refit	
--------	--	---	---	--

Job - 4;DOOR BEND (NEEDED DENTING & PAINTING)

Sublet		0	Consumable (painting material & etc	
Sublet		0	Front panel remove & refit	
Sublet		0	Rhs bumper corner, middle bumper remove & refit	
Sublet		0	Both side headlight assembly remove,repair & refit	
Sublet		0	Lhs headlamp panel remove,repair & refit	
Straight		0	Both side headlamp wiring remove,repair & refit	2.5
Sublet		0	Lhs door removed,repair,refit	

Job - 5;L.H.S. WHEEL STUD NEED TO BE REPLACED

Standard Times	77344-2	0	Wheel stud, front, replace lhs all	0.7
----------------	---------	---	------------------------------------	-----

Job - 8;GENERAL CHECK UP

Standard Times	17744-2	8	General checkup done	1.2
----------------	---------	---	----------------------	-----

Cust.	1093416	Delhivery Limited		
Order	66898	Dealer	69100	
Repair Date	08/04/2025	Closed Date	09/04/2025	Order Delv.dt 08/04/2025
Chassis/SL No.	8-992520	Regn.	KA51AK7764	Vehicle Delv.dt 14/11/2024
Mileage	103349	Operation Hrs	2374	ServiceType 0
Contr.ID	2509120514	Contr.Startdt	01/01/2025	Contr.Expirydt 31/12/2029

Line Type	Lab/Part	Payment Code	Description	Qty
-----------	----------	--------------	-------------	-----

Job - 1;Basic Service 100,000 Km Done

Sublet	2300000	8	Both Fuel Tank Strap rubber Molding replaced	
Parts	VO990962	8	FLANGE LOCK NUT	4
Parts	VO20493836	8	RUBBER MOULDING	1.5
Standard Times	17700-2	8	Basic Service 100,000 Km Done	4
Parts	VO21337557	8	FILTER	1
Parts	OL23068345S-I	8	VOLVO ENGINE OIL VDS-4.5 - 1 Ltr	38
Parts	VO21954674	8	STRAINER	1
Parts	VO23690622	8	SERVICE KIT	1
Parts	VO24633960	8	FILTER KIT	1
Parts	VO24137737	8	FILTER KIT	1
Parts	VO23759508	8	OIL FILTER KIT	2

Cust.	1093416	Delhivery Limited		
Order	3257	Dealer	694038	
Repair Date	18/03/2025	Closed Date	20/03/2025	Order Delv.dt 18/03/2025
Chassis/SL No.	8-992520	Regn.	KA51AK7764	Vehicle Delv.dt 14/11/2024
Mileage	75195	Operation Hrs	1623	ServiceType 1
Contr.ID	2509120514	Contr.Startdt	01/01/2025	Contr.Expirydt 31/12/2029

Line Type	Lab/Part	Payment Code	Description	Qty
Job - 1;Pay code - 8 Engine oil level found low.				
Text		8	As per communication with driver engine oil top up from customer Volvo hub stock.	
Parts	OL85153938	8	ENGINE OIL VDS5 210 LTR	7

Cust.	1093416	Delhivery Limited		
Order	4377	Dealer	69203	
Repair Date	13/03/2025	Closed Date	13/03/2025	Order Delv.dt 13/03/2025
Chassis/SL No.	8-992520	Regn.	KA51AK7764	Vehicle Delv.dt 14/11/2024
Mileage	30	Operation Hrs		ServiceType 1
Contr.ID		Contr.Startdt		Contr.Expirydt

Line Type	Lab/Part	Payment Code	Description	Qty
Job - 1;				
Text		9	H0006 Campaign performed date 11/12/2024	
Standard Times	28005-2	9	EMS/ECM, software update	0.2
Standard Times	17010-2	9	Connect-disconnect of diagnostic tool	0.2

Cust.	7901	Volvo Group India Pvt. LTD.		
Order	96232	Dealer	69300	
Repair Date	07/11/2024	Closed Date	12/11/2024	Order Delv.dt 08/11/2024

Service History

Page 5 / 6

Chassis/SL No.	8-992520	Regn.	Vehicle Delv.dt	14/11/2024
Mileage	30	Operation Hrs	ServiceType	0
Contr.ID		Contr.Startdt	Contr.Expirydt	

Line Type	Lab/Part	Payment Code	Description	Qty
Job - 1;				
Parts	OL85153938	2	ENGINE OIL VDS5 210 LTR	2
Parts	OL85109697-AIBC	2	Adblue - IBC	15
Straight		2	Labour charges towards complete vehicle software update	1
Straight		2	Labour charges towards conversion kit F&E activate	0.5
DAT	8840000	3	PARAMETER PROGRAMMING	0.5
Standard Times	17102-2	3	Delivery service	3.5

Cust.	7901	Volvo Group India Pvt. LTD.		
Order	95931	Dealer	69300	
Repair Date	23/10/2024	Closed Date	24/10/2024	Order Delv.dt 23/10/2024
Chassis/SL No.	8-992520	Regn.	Vehicle Delv.dt	14/11/2024
Mileage	30	Operation Hrs	ServiceType	0
Contr.ID		Contr.Startdt	Contr.Expirydt	

Line Type	Lab/Part	Payment Code	Description	Qty
Job - 1;				
Parts	VO984733	9	FLANGE SCREW	3
Parts	VO969445	9	FLANGE SCREW	24
Parts	VO948610	9	O-RING	1
Parts	VO874393	9	HOUSING	1
Parts	VO469846	9	SEALING RING	1
Parts	VO24470463	9	PRESSURE PIPE	1
Parts	VO24152701	9	COVER	1
Parts	VO24118272	9	SEALING STRIP	1
Parts	VO23823960	9	OIL FILTER KIT	2
Parts	VO23545374	9	OIL STRAINER	1
Parts	VO22645240	9	SEALING RING	2
Parts	VO22416685	9	REDUCTION VALVE	1
Parts	VO22275838	9	SEALING RING	2
Parts	VO21092243	9	SEALING RING	2
Parts	VO20824914	9	SUCTION PIPE	1
Parts	VO20824906	9	OIL PUMP	1
Parts	VO20579690	9	GASKET	1
Parts	VO1161231	9	SEALING AGENT SILICONE	1
Parts	OL85153938	9	ENGINE OIL VDS5 210 LTR	35

Service History

				Page 6 / 6
Standard Times	28005-2	9	EMS/ECM, software update	0.2
Standard Times	22132-2	9	Turbo pressure hose, replace	3
Standard Times	17010-2	9	Connect-disconnect of diagnostic tool	0.2
Text		9	OLD:T240009200887 NEW:17643	